


Edloe Street Pathway Improvements – Project Report # 3  
May 6 – July 28

Highlights

- Project Management Group, LLC (PMG) continued installation of the fence along the pathway and grading the area.
- Installation of landscape along the path is almost complete and irrigation has been installed and currently watering the landscape that is in place.
- Grading of the pathway and the installation of limestone to provide a subbase for the porous pave surface has been laid down along the pathway.
- Installation of cement pads for the benches along the pathway have been poured.



Photos







Photos Continued



Photos Continued

